


Parts Breakdown—Cobra Series Standard and High Output Models with Remote Electronic Ballast



Item No.	Description	Part No.	Quantity required			
			CB1-S	CB1SS-S	CB1SS-HO	CB1-HO
1	Power Supply	BLSTA0007 BLSTA0009	1	1	1	1
*2 *2a	Compression Nut	CN0007	1	1	1	1
	Compression Nut	CN0008	1	1	1	1
	Compression Nut	CN0042	2	2	2	2
	Compression Nut (lamp harness end)	CN0043	1	1	1	1
	Compression Cap for CN0043	CN0044	1	1	1	1
*Compression Nuts vary depending on chamber						
3	Sleeve O-Ring, EPDM	ORNG0009	2	2	2	2
4	Standard Output Lamp—254NM	GL-5463-4S74R		1		
	Standard Output Lamp—254NM	GL-5843-4S74R	1			
	Standard Output Lamp—185NM	GV-5843-4S74B	1			
	High Output Lamp—254NM	GL-5463-4H74Y			1	
	High Output Lamp—254NM	GL-5843-4H74Y				1
	High Output Lamp—185NM	GV-5843-4H74A				1
5	Quartz Sleeve, Open	BA-Q7		1	1	
		BA-Q15	1			1
6	UV View Port	VPM0001	1	1	1	1

CobraUV™ Series Remote Electronic Ballast

